


Hydration state?

Darr drying


heating + weighing



Duration: ~3 days




Location: lab only




Calcium-carbide-method

crushing for pressure reading



Duration: ~30 minutes



Location: construction side + lab

